

Message

From: Shewmake, Kenneth [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=5031C1ABFE8847809A448EF4899DE65C-SHEWMAKE, KENNETH]
Sent: 3/22/2019 8:01:22 PM
To: Rebecca Storms [Rebecca.Storms@Tceq.Texas.Gov]; Pereira, Stephen (pereira.stephen@epa.gov) [pereira.stephen@epa.gov]; Kessinger, Jessica (DSHS) (Jessica.Kessinger@dshs.texas.gov) [Jessica.Kessinger@dshs.texas.gov]; Rauscher, Jon (Rauscher.Jon@epa.gov) [Rauscher.Jon@epa.gov]; Tsui-Bowen, Alethea (Tsui-Bowen.Alethea@epa.gov) [Tsui-Bowen.Alethea@epa.gov]
Subject: FW: revised figures for Lane Plating
Attachments: Figure 8_LP_CSMTM_Eco_SW.pdf; Figure 5_LP_CSMTM_HH_Soil.pdf; Figure 7_LP_CSMTM_HH_SW.pdf; Lane CSMTM_Table 3.pdf; Lane CSMTM_Table 1.pdf; A2_Sap_LP_Soil.pdf

The following are the revised figures from the Lane Plating CSMTM and the SAP. We were concerned that the 3-15 version of these figures had non-detects, where benchmarks were lower than detection limits, marked as exceeding residential and Industrial benchmarks. Please let me know if you have any issues with these revised figures by Monday morning. We need to get these documents on the website, and we need to make the CSMTM and SAP final so we can prepare for field work in May.

Thanks,

Kenneth Shewmake
US Environmental Protection Agency
Environmental Scientist
RPM lane Plating

1445 Ross Ave., Suite 1200
Dallas, TX 75202-2733
shewmake.kenneth@epa.gov
work phone- (214) 665-3198



From: Paddack, Mark <mpaddack@eaest.com>
Sent: Friday, March 22, 2019 2:47 PM
To: Shewmake, Kenneth <shewmake.kenneth@epa.gov>
Subject:

Mr. Shewmake:

As we discussed, please find attached the CSMTM Figures and Tables, which were revised per recent comments. Also find attached a copy of Figure A-2 from the SAP, which was laso revised per these recent comments.

Please let me know if you have questions or comments concerning this matter.

Thank You,
Mark Paddack
EA Project Manager